









EVO 79-599

Heat Exchanger Maintenance Kit

MNT 94309 B



<p>FIB 74902 Insulation Rear Wall</p> 		<p>FIB 74007 Insulation Burner Door</p> 		<p>GKT 74035 Gasket Burner Door</p> 	
<p>MSC 74029 Insulation Washer (Rear Wall Insulation)</p> 		<p>MSC 74028 Screw for (Rear Wall Insulation)</p> 		<p>PLT 94318 A Ignitor Replacement Kit</p> 	
<p>Ignitor Adjustment/Mounting Instructions</p>					
<p>~5/16" (8-10mm)</p> 			<p>~1/8" (3.50mm)</p> 		

Note: Drawings enlarged to show detail. Not drawn to actual proportion.