








EVO 129-599

Heat Exchanger Maintenance Kit

MSC 74208A

<p>FIB 74098 Insulation Rear Wall</p>	<p>FIB 74093 Insulation Burner Door</p>	<p>GKT 74035 Gasket Burner Door</p>
		
<p>MSC 74029 Insulation Washer (Rear Wall Insulation)</p>	<p>MSC 74027 Screw for (Rear Wall Insulation)</p>	<p>PLT 74317 Ignitor Replacement Kit</p>
		
<p align="center">Ignitor Adjustment/Mounting Instructions</p> 		

Note: Drawings enlarged to show detail. Not drawn to actual proportion.